



500 EAST

KEY NOTES:

- 1. Picnic shelter
- 2. Streambank restoration
- 3. Mown grama grass
- 4. Interpretive Signage
- 5. Unmown short grama grass
- 6. Butterfly meadow
- 7. Fountain sculpture
- 8. New pedestrian bridge
- 9. Mounding
- 10. Existing bench
- 11. Repair/replace existing block wall & mural
- 12. Trailhead signage
- 13. Stream access point
- 14. Seatwall

LEGEND

- Existing tree (to be removed)
- Existing shade tree
- Proposed shade tree
- Grama Grass Lawn
- Streambank Restoration
- Stone Dust
- Butterfly Meadow
- Butterfly Host Shrubs
- Existing Bench (Relocated)
- Rocks
- Trailhead Signage